

Shasta Water Association Dam Restoration

APPENDIX A Project Photos



Demolition of the pump station and dismantling of the old pumps.



Completion of the fish screen's brush arm assembly.

Shasta Water Association Dam Restoration



Backfill of fish screen and demolished pump station.



Salmon were observed swimming up the lower boulder riffle.

Shasta Water Association Dam Restoration



Fish salvage by CDFG in the temporary bypass channel before backfilling.



Installation of wetwells.

Shasta Water Association Dam Restoration



CDFG fly over of the project site. Photo showing the river back in its channel and the temporary bypass channel prior to backfilling.

Shasta Water Association Dam Restoration

APPENDIX A PHOTOS



Revegetation of disturbed streambanks both upstream and downstream of the SRWA fish screen. The t-posts support wire cages placed around willow plantings to prevent damage from local beavers.



Boring underneath a Siskiyou County Road, railroad track and fiberoptic line for the Upper South Ditch pipeline.



Contractors eager to begin work again on the Upper South Ditch pipeline project.